


INSTRUCTION

Forza 720B

● How to update the firmware of Forza 720B:

1. Download the firmware installation package from the website.
2. Put the firmware files of light fixture and control unit into the root directory of the USB drive (make sure the versions of the two firmware files are matched).
3. Inset the USB flash drive into the USB port.
4. Enter the MENU and rotate "Right knob" to FIRMWARE UPDATE.



5. Press "Right knob" to enter the interface to search for the firmware files.



6. After the firmware is found, rotate "Right knob" to select the "UPDATE" to start firmware update.



7. After the firmware update is completed, the fixture will automatically restart and run normally.

● **Precautions:**

1. Please do not rename the firmware file.
2. Ensure the USB flash drive is formatted to FAT, FAT32 or exFAT.
3. If prompted that "PLEASE CONNECT THE LAMP HEAD TO THE CONTROLLER BEFORE FIRMWARE UPDATE", please check whether the light fixture is connected to the control unit or whether loose connection occurs.
4. If prompted that "THE VERSIONS OF THE TWO FIRMWARE FILES DON'T MATCH, PLEASE CHECK THE FILES AND TRY AGAIN", please check whether the versions of the two firmware files are consistent.
5. If prompted that "MISSING PARTS OF FIRMWARE FILES,PLEASE CHECK THE FILES AND TRY AGAIN", please check whether there are two firmware files in the USB drive.
6. If prompted that "NO FIRMWARE FOUND", please check whether the firmware files are correct, whether the firmware files are stored in the root directory of the USB flash drive, or whether the USB flash drive format is FAT, FAT32 or exFAT.
7. If all the above steps are done and the firmware files still cannot be found, try to re-format the USB flash drive and update again.
8. If the light fixture still cannot identify the USB flash drive, please replace the USB flash drive.