

# **FIRMWARE UPDATED CONTENT AND FUNCTION DESCRIPTION**

**Evoke 2400B V1.05.07**

Version	Upgraded	Firmware Version	Date
V1.0	<ol style="list-style-type: none"> <li>1. Optimize Nanlink APP control function.</li> <li>2. Add control function for the wired controller.</li> </ol>	Evoke_2400B_Drv_Fw_V1.03.07 Evoke_2400B_Ctrl_Fw_V1.03.07 Evoke_2400B_Data_Fw_V1.03.07	2024-01-15
V2.0	<ol style="list-style-type: none"> <li>1. Added the control function for FL-35E, enabled the control function for FL-35E by Nanlink App and DMX console.</li> <li>2. Optimized the electronic contacts recognition function.</li> </ol>	Evoke_2400B_Drv_Fw_V1.04.04 Evoke_2400B_Ctrl_Fw_V1.04.04 Evoke_2400B_Data_Fw_V1.04.04	2024-04-19
V3.0	<ol style="list-style-type: none"> <li>1. Fixed control issues in the menu of the wired controller.</li> <li>2. Fixed the flickering issue with Lumenradio control at long-distance critical points.</li> <li>3. Optimized modifier control functionality.</li> </ol>	Evoke_2400B_Drv_Fw_V1.05.07 Evoke_2400B_Ctrl_Fw_V1.05.07 Evoke_2400B_Data_Fw_V1.05.07	2024-05-21

- **Evoke\_2400B\_Fw\_V1.03.07**

**Updated Content Description:**

1. Optimize Nanlink APP control function.
2. Add control function for the wired controller.

- **Evoke\_2400B\_Fw\_V1.04.04**

**Updated Content Description:**

1. Added the control function for FL-35E, enabled the control function for FL-35E by Nanlink App and DMX console.
2. Optimized the electronic contacts recognition function.

- **Evoke\_2400B\_Fw\_V1.05.07**

**Updated Content Description:**

1. Fixed control issues in the menu of the wired controller.
2. Fixed the flickering issue with Lumenradio control at long-distance critical points.
3. Optimized modifier control functionality.